## IN THE UNITED STATES PATENT & TRADEMARK OFFICE

ATTORNEY DOCKET NUMBER: 200208474-1

IN RE APPLICATION OF: U.S. Patent No. 7,800,253

USPTO CONFIRMATION CODE: 7631

APPLICATION NO.: 10/743,230

FILED: Dec. 21, 2003

EXAMINER: ROBERT L DEBERADINIS

**GROUP ART UNIT: 2836** 

FOR: TRANSMITTING SIGNALS OVER INTERCONNECT CARRYING DIRECT CURRENT FROM POWER SUPPLY TO ELECTRONIC DEVICE

## 37 CFR 1.322 & 37 CFR 1.323 REQUEST FOR CERTIFICATE OF CORRECTION

#### HONORABLE COMMISSIONER OF PATENTS & TRADEMARKS

Sir:

The following is a request for a certificate of correction in Serial Number 10/743,230, now Patent Number 7,800,253.

A certificate of correction under 35 USC 254 is respectfully requested in the above-identified patent.

⊠ fee is r	All errors were the fault of the USPTO, no fee required. In the event that a further equired, please charge the amount to Deposit Account No. 082025.
	All errors were the fault of the applicant and, accordingly, please charge \$100.00 Deposit Account No. 082025. In the event that a further fee is required, please the amount to the same Deposit Account.
	The errors were the fault of both the applicant and USPTO and, accordingly, charge \$100.00 to our Deposit Account No. 082025. In the event that a further fee ired, please charge the amount to the same Deposit Account.

The exact location where the error appears in the patent and patent application is as follows:

In column 9, line 46, in Claim 21, delete "components" and insert -- components, --, therefor. (Amendments to claims filed on Mar. 8, 2010, page 7, in claim 24, line 3)

The requested correction is attached on Form PTO 1050.

Respectfully Submitted

26 February 2011

DATE

/Steven R. Ormiston/

Name: Steven R. Omniston Registration No.: 35974

Attorney/Agent of Record

HEWLETT-PACKARD COMPANY Intellectual Property Administration 3404 E. Harmony Road Mail Stop 35 Fort Collins, CO 80528

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 1 of 1

(Also Form PTO-1059)

PATENT NO. : 7,800,253

APPLICATION NO.: 10/743,230

ISSUE DATE : Sep. 21, 2010

INVENTOR(S) : Nikholas Hubbard et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 9, line 46, in Claim 21, delete "components" and insert - - components, - -, therefor.

## MAILING ADDRESS OF SENDER (Please do not use customer number below):

Hewlett-Packard Company Intellectual Property Administration 3404 E. Harmony Road Mail Stop 35 Fort Collins, CO 80528

This collection of information is required by 37 CFR 1.322, and 3.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C 122 and 37 CFR 1.14. This collection is estimated to take 1.0 from to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commence, P.O. Box 1450, Alexandria, VA 22313-1450, DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patent, P.O. Box 1456, Alexandria, VA 22313-1450.